



KMG Europe BV
Parallelweg 35
7161 AE Neede
Tel: +31-(0)545-294545
Fax: +31-(0)545-291306
E-mail: factory@kmg.nl
Internet: www.kmg.nl

VAT NL: 8054.40.495.B01
Chamber of commerce: 08073397

BIC / SWIFT: ABNANL2A
IBAN: NL74ABNA0561500509

Naam

For your information Urgent

Neede, 27 August 2007

From : A.L.P. Kroon

Subject : Gusset plate modification Afterburner ride

Order no. :

Our reference : FRB-24-XX

To all Afterburner owners,

On August 8th, KMG released service bulletin FRB-SB006. In this bulletin it was stated that all Afterburner models, need to have gusset plates welded on the swing arm to bearing flange connection.

In this service bulletin it was not specified by which date the modification needed to be issued. The reinforcement gusset plates of the swing arm bearing flange should be installed before November 30th, 2007.

Until this date, regular visual inspection of the affected weld area is strongly recommended, and should be registered into you ride's logbook.

A summary of actions regarding FRB-SB006 is given below:

NDT inspection of the affect weld area according FRB-SB006	:	Immediately
Repair of discovered cracks	:	Immediately
Inspection of affected weld area between NDT testing and installation of gusset plates	:	Each day
Installation of gusset plates	:	Before November 30 th , 2007

I hope to have you informed sufficiently.

Kind regards,

A.L.P. Kroon